

T30 N 40 E M D M

Field Notes of the Survey of the Subdivision
Lines in T30 North R40 East
M D M

Subdivision began Nov 20. 1843
The central ^N Eastern portions of this
township being barren broken and
rocky mountains. I commenced at
the corner to Sections 31nd & 32nd on the
South Boundary and run thence

North between Sections 31nd & 32nd
T30 N 40 E East

- 40.00 Along N slopes of Mts near summit
For 1/4 Sec lot, put a granite stone 15x10x6
8 in in ground marked 1/4 on N side
- 80.00 For lot to Sec 29, 30, 31nd & 32nd, put a Flint Rock
18x12x4 10 in in ground, marked 1 notch
on S^{side} 5 notches on E sides