

Set Tps 32133 to Pos E. M. D. M.

From the corner to Tps 32133 to Ego vsw E
on the Rocky Valley Guide meridian
Iron,

+

Meton true line between 36 & 1.

Tarry 130° E

40.00 Set a charred post 4 ft x 3 x 3 in. 12 in in ground
made mound 24 in high. dig pits 24 x 12 x 12
for 1/4 sec cor

80.00 Set a charred post 4 ft x 3 x 3 in. 12 in in ground
made mound 24 in high. dig pits 24 x 12 x 12
for cor to Sec 1. 2. 35. 36

Land rolling soil 3rd rate
Sage brush. bunch grass

+

Meton true line between 2 & 35

40.00 Set a charred post 4 ft x 3 x 3 in. 12 in in ground
made mound 24 in high. pits 24 x 12 x 12. for 1/4 sec
80.00 Set a charred post 4 ft x 3 x 3 in. 12 in in ground