

To determine proper adjustment
of compass for subdividing
Township 47 N Range 38 East
I commenced at the South East
Corner of township and I ran
south on a plank line, along
the East boundary of section
36 -

On $18^{\circ}15' E$ -

40.04 to a point 2 links East of
the $\frac{1}{4}$ Sec. Cor

80.06 to a point 4 links East of cor.
to sec 25 and 36 -

Again

From the South East corner
of township I ran on a
plank line, South $88^{\circ}20'$
West -

On $18^{\circ}15' E$

39.88 to a point 3 links South of
 $\frac{1}{4}$ Sec. Cor -