

Sub. T 35 N R 19 E M. D. M.

Sec. 12. 1112 fumer which Cu Pan

S 89.32 W on line bet. Sec. 2, 11

Var. 17.13 E.

40.12 Set trap stone 6.8.16 8 in ground

dig 2 pits 72 12 24 W. 4/4 full acc. cor.

80.24 The Cu h. Secs. 2, 3, 10, 11. fully cutting and

level sage bunch grass soil 1st. cat.

North on line bet. Secs. 2, 3

Var. 17.13 E.

40.00 Set trap stone 7.9.16. 8 in ground

dig 2 pits 12 12 24 W. 4/4 full acc. cor.

80.86 West-Serenth Standard North 4.36

chs E of Standard Cu h. Secs. 34, 35.

Set trap stone 8.10.22 12 in ground

dig 3 pits 72 12 24 6 notches S 2 E 11 W

W. C. C. for Chasing Cu. h. Secs. 2, 3

fully sage bunch grass soil 1st. cat.

stop

Jan. 31st 1880.

f