

Exteriors T40N R65E MDM¹⁷

Repace

Having examined the 8th Standard through range 65 East, from the S.W. cor of sec 31 T41N - East to the S.E. cor of the Twp. I find the old willow posts together with mounds and ^{and the distance between the Range lines of Township 48th 50th} trace of pits - but the alignment I find to be S 89° E instead of East as reported in notes furnished me by the Surveyor General, which notes report an erroneous variation as proven by my observation reported herewith.

Running East on the S bdy of Sec 36. T41N R65E I find at

57.50

The old closing corner for the NE cor sec 1 T40N R65E which is a willow post 2" square properly marked lying on mound