

Resurvey/80

Exterior T39N R68E MDM

East Boundary

Oct 17th Having examined the W bdy of T39
NR69E. and finding some of the corners
obliterated and others defaced I resurvey
as follows.

Commencing at the cor To Twp39th 40 N
TR69E. as hereinbefore described I run
S on W bdy S. 6.

Ta. 17° 30' E

40.00

No. cor. set. Temporary piece cor

80.00

Old cor a mallow post 3 ins in dia.
lying on ground 2^{ch} 8^{els} W of line.
rebuild as follows. Set a post 4 ft long
4 ins sq with marked stone 12 ins in
the ground for cor to sec. 16 & 7 & 12.
marked

T39N S 60m NE

TR 69 E S 70m SE

TR 68 E. S 12 on SW