

Exterior T36 N. R35 E - Continued

Chains

Chains

Sage brush entire mile.

North lot Secs 1 & 6.

Var 17° 50' E.

Descending.

40.00

Deposit a marked stone 12 ins in the ground for $\frac{1}{4}$ Sec Cor. dug pits 18x18 x 12 ins N & S of cor. 5 $\frac{1}{2}$ ft dist and raised a mound of earth 1 $\frac{1}{2}$ ft high 3 $\frac{1}{2}$ ft base over it. In N pit drove a stake 2 ft long 2 ins square 12 ins in the ground marked $\frac{1}{4}$ Sec N face.

80.00

Deposit a marked stone 12 ins in the ground for Cor to Tp 36 & 37 N. R's 34 & 35 E, dug pits 24x18x12 ins lengthwise on each line, N-S-E & W. of cor 6 ft dist and raised a mound of earth 2 $\frac{1}{2}$ ft high 5 ft base over it. In S pit drove a stake