

Connecting Lines. Halleck

Thence Iron S. bet sec. 3-4

Va. $17^{\circ}30'$ E,

- 40.80 Found $\frac{1}{4}$ sec. post floating,
no evidence of mound & pits.
- 80.60 No evidence of sec. cor.-
on creek bottom subject to
overflow.
- 120.60 Still on creek bottom -
no evidence of cor.
- 161.90 Found cor. to sec. 9-10-
15; and 16, which is a
post 4 ft. long 4 in. sq. lay-
on mound of earth
with pits - post marked
ed - $T. 35^{\circ}N.$, $R. 58^{\circ}E$, $S. 10.$,
 $S. 15.$, $S. 16$, $S. 9$ on
the four faces respectively.
Re-set post in mound of
earth, plug pits $18 \times 18 \times 12$ in.
~~in each sec.~~
~~N. E. S. & W. of post $6\frac{1}{2}$ ft. dist.~~