

GENERAL DESCRIPTION.

The North half of this township & the south west quarter contain some excellent agricultural land should water be conducted upon it.

The remainder of the land affords excellent grazing

This township is poorly watered, the only stream being Mack's Creek which runs no water over these lands except in spring floods.

All post set are of redwood.

It was necessary to resurvey the exterior reported with ~~with~~ this work in order to have the necessary corners ~~from~~ which to start & close my survey.