

East boundary ³⁴⁰ S. 18 N. R. 50 E.

9

May 22nd 1893

I now return to Cor. to Tps. 17^E 18^N
Rs 60^E 61^E 62^E 63^E 64^E 65^E 66^E 67^E 68^E 69^E 70^E 71^E 72^E
line bet. Secs 31^E & 36^E with 16^E 65^E
at 40.60 I find old 1/4 sec cor. & at
81.54 find the Sec Cor to be 30^E 65^E 66^E
I therefore continue the true line
north & find that no portion of this
East boundary is in alignment or
correct for distance. But that the
cor. to Tps 18^E 19^N. Rs 60^E 61^E 62^E 63^E 64^E 65^E 66^E 67^E 68^E 69^E 70^E 71^E 72^E
1 ch & 6 miles 8 ch & 67^E 68^E north of the Starting Cor.
As Tps 18^E 19^N R 61^E has not been
subdivided & consequently no sub-
division lines have been closed on
either side of this E. boundary. I
resurvey the same as follows

From Cor. to Tps 17^E 18^N Rs 60^E 61^E 62^E 63^E 64^E 65^E 66^E 67^E 68^E 69^E 70^E 71^E 72^E
I run N. 13^E 14^E bet Secs 31^E & 36^E
Var 16^E 65^E 66^E 67^E 68^E 69^E 70^E 71^E 72^E

ascend gently thro dense sage
wood set cedar post 4" dia. 12" in
ground for 1/4 sec cor. marked "1/4"
on N. face. aug pits 18 x 18 x 12 N. & S.
6 1/2' dist. raised mound of earth 2' high