

North Boundary

At 8 a.m. June 2nd 1896 I find by observation on the line run by me for the East boundary of T. 18. N. R. 50 E the magnetic variation to be 17.05 E.

From the cor. to Tps. 18 & 19 North

Ranges 50 & 51 East I run N 89.57 E on a blank line between Sections 6 & 31 with a bearing of 17.05 and at 3980 chs find the $\frac{1}{4}$ sec. cor. to be at 15 links and at 7980 chs find the Section cor. to be at 28 links

I continue the line and find the old line incorrect both as to course and distance with several corners missing & others much dilapidated but at 6 miles 1 chain 40 links find cor. to Tps 18 & 19 North R. 51 & 52 E. to bear N. 1 ch. 168 links

As T. 19 N. R. 51 E has not been subdivided & consequently no subdivision lines have been closed on this North boundary I therefore resurvey the same as follows