

East Boundary

15

2. 18. 7. R. 51 E.

At 2 p.m. June 30th 1893 I find by observation on the line run by me for the South boundary of Tp. 18 N. R. 51 E. the magnetic variation to be $16^{\circ}55' E$.

From the cor. to Tps. 17 & 18 N. Rs. 51 & 52 E. ^{which is a post put in wrong place & properly marked & replaced} I run North on a blank line between Secs 31 & 36 with $\text{Var. } 16.55 E$ and at 40 chains after diligent search am unable to find any trace of the old $\frac{1}{4}$ Sec. cor. I therefore continue on the same course and at 80 chs after diligent search can find no trace of the Section corner

I therefore continue on the same course and find that no portion of this line is correct either for distance or alignment but at 6 miles 11.60 chains find the cor. to Tps. 18 & 19 N. Rs. 51 & 52 E. to bear West 70 links

As Tp. 18 N. R. 52 E. has not been subdivided and consequently no subdivision lines have been closed on this East boundary I therefore resurvey the same as follows