

4

In order to ascertain the position of the S. E. corner of the township I run S. on a black line from the closing corner to Tps. 25 N. R. 34 & 35 E which is a mound with traces of pit 3 chs & 60 links east of the standard corner as described in the notes supplied by the Surveyor General, and find the corners much effaced and several missing but that the corner to Tps. 24 & 25 N R. 34 & 35 E is due south of my starting corner 5 miles 78 chs and 69 links distant

I therefore re-survey this line as follows.