

Exterior T. 40 N. R. 64 E. M. Dm

July 16th

In order to ascertain the condition of the old corners on the west boundary from which to commence my work of subdivision I go to the Standard Corner to T. 41 N. R. 63 + 64 E whence I run west along the Eighth Standard with Var. 17° 36' E. 24 chs. 56 lks at which point I am unable to find any trace of old Township corner.

Thence I run S on a blank line with same variation and find a few of the old corners ^{chain west} which are much defaced, the remainder obliterated and at 6 miles find the old corner to Townships 39 + 40 N Ranges 63 + 64 E ^{chain west} which is a