

Section T. 35 N. R. 55 E. M. 50

Having examined the south boundary
by the Guide Meridian & found the old
corners in such a state of obliteration and
decay as to necessitate a re-survey I
therefore re-trace these lines as follows:

At 7 am. Sept. 11th 1894 I set over the
S. E. corner of this township & find the
variation of the meridian established
by me last night to be $17^{\circ}30' E$.

At this point I verify the adjustments
of my instrument and find them
correct.

From the corner to Tps. 34 & 35 N.
R. 55th & 56 E which is a mound
with pits & fragment of post with
marks partly legible I run,