

Township 36 N.

Range 20 E

M D

Meridian.

Continuing my blank line on the west board and I find all the corners in good alignment properly marked as described in the original field notes & the chaining approximately correct

At 489 chs 17 lks I find the standard corner to Tps 35 & 36 N. Rs 21 & 22 E which is a stone family set & properly marked as described in the field notes supplied by the Surveyor General.

I now run on a blank line on the 7th standard parallel and at 39-01 chs find 1/4 sec. cor as described and at 79-21 find the standard cor to secs 31 & 32 which is a stone family set & properly marked as described in the field notes;

at 118-09 chs find 1/4 sec. cor
148-13 " " stand. cor. to secs 32 & 33 which is a post in ground as described. continuing the blank line I find the old survey correct as to alignment but with errors as to