

## South Boundary of T. 30 N. R. 55 E. 1/4 Sec. 2

In order to ascertain the condition of the South boundary on Sept 4. 1896 I retrace the same & find the line fairly correct as to alignment & distance but several corners obliterated. I therefore re-survey the same as follows.

From the corner to Secs. 1 & 2,  
~~34~~ 35 & 36 on the S. bdy I run  
 N 89.55 W. bet sec. 2 & 35.

4000 After diligent search I am  
 unable to find any trace of  
 old 1/4 sec. cor.  
 Set a redwood post 3 ft. long  
 3 ins. sq with marked stones  
 24 ins. in the ground for 1/4  
 sec. cor. marked 1/4 S on N