

Subdivisions of F31A R55C.

In retracing the line N. from this point
I find the old corner missing & no
agreement with the topography when
same is shown in the old field notes

Therefore re-survey the same as follows

N. Secs. 35 & 36

1700 Over rolling land
4000 ^{road, road of 1888} No trace of old 1/4 sec. cor.

Set a redwood post 3 ft long 3 ins sq
with marked stone 24 ins in the ground
for 1/4 sec cor marked 1/4 on W. face,
dug pits 18 x 18 x 12 ins N & S. 3 ft distant
raised a mound of earth 3 1/2 ft base
1 1/2 ft high W of cor.

8000 After diligent search I am unable to
find any trace of old sec. cor.

Set a redwood post 3 ft long 4 ins sq.