

121
Estuirs of T. 31 N. R. 52 E.

On November 14th 1896 After diligent search I am unable to find any trace of old corners on the range line bet Tps. 32³³ N. R. 52 + 53 E. I therefore go to the box to Tps. 33 N. R. 52 + 53 E which is a firmly set & properly marked & witnessed agreeing with Surveyor General's notes & retrace the range line south and find no trace of old corners and the topography to be entirely different from that reported in the notes.

Knowing that I shall be unable to make the subdiviserial survey of Tps. 32 N. R. 52 + 53 E without considerably exceeding the amount of the liability of my contract, and as much as T. 32 N. R. 52 has been subdivided and as in order to determine the