

~~117~~

.316

Subdivision of.

8656 Intersect s. bdy of Tp. 56 R. East of cor.
set for standard cor to secs 33 & 34 which
is a rock firmly set & properly marked
& witnessed a decree with Murray General's
field notes. I destroy all traces of this old
cor. and at the point of intersection set
the same stone which is lava 18 x 11 x 9 ins. 12 ins
in the ground for standard cor to secs 33 & 34
marked & cor with 3 grooves on E & W
faces & raised a mound of stone 3 ft. base 2 ft.
high N of cor.

I destroy all traces of the 1/4 sec. cor on
the s. bdy of sec 34 & re-establish the same
on the same line as the 36 R. westward by setting
the same stone 12 x 9 x 8 ins. 11 ins in the ground
for 1/4 sec. cor marked on N face and raised
a mound of stone 3 ft. base 2 ft. high N of cor.