

E and N Bay T 38 N P 54 E

May 4-1900. I begin at C.W. of T 37
and 38 N T's 54 and 55 E as
reestablished by me and run
N into on a flank line at

40.00 find no trace of old C.W.

80.00 find decayed stake and trace
of pits & mud on line. Thence
I continue North and find
almost no trace of old C.W. and
after enter hills topography does
not agree. At 6 miles I am
unable to find any trace of T's
C.W. I go to 1/4 C.W. on S side of sec
35. Shown me by Mr. Reed
previous to beginning survey
from said C.W. I run E on flank
line.

40.45 Old C.W. 35 and 36 kers 520 kers dist.
Thence E on S Bay 36.

40.00 find no trace of 1/4 C.W.

73.76 Put N and S line 8.90 chs S of 6 mile
point I continue line

80.00 Make thorough search but find
no trace of T's C.W.

From 80.00 ch point I run South
but find no trace of C.W.
I resurvey North and E sides as follows.