

North Bdy, T. 33 N, R. 38 E

May 3rd. 1904. at 8^h 00^m a.m.
 l.m.t. I set off. $40^{\circ}46'N$, on lat
 arc. $15^{\circ}41'N$, on decl arc, and
 determine a meridian with
 the solar at the cor. of Tps. 33
 and 34 N, Rs. 37 and 38 E
 which is a cedar post 4^{1/2} ft. sq.
 Marked and witnessed as
 described by the U.S. Surveyor
 General for Nevada. This is the
 Tp. cor. found and reported by
 G. O. Choney U.S. Examiner of
 Surveys, and from this cor.
 I run East on a flank line
 to locate proper position of N. Bdy,
 of T. 33 N, R. 38 E. At 38.20 Chs.
 find no trace of $1/4$ sec. cor. I
 continue East. and at 78.20 chs.
 find nothing I can indentify as
 old cor. of sec. 5. 6-31 and 32.
 I continue East on flank line
 and at 159.50 chs. old cor. of sec.
 4-5, 32 and 33, hors S. 15 lks,
 dist. Old cor. is a stake
 badly decayed with markings
 almost obliterated and trees