

Resurvey of the W. Bdy. T. 32 N. R. 39 E.

Chs. From the cor. of Tps. 32 and 33 N.
Rs. 38 and 39 E. heretofore
described. I run
South on a random line
let Sec. 1 and 6.

39.75 Find trace of old mound
and pits. No stake or stone
79.70 Trace of old mound and pits
and decayed stake markings
almost obliterated. I continue
South on flank line and at
480.54 Chs. The old cor. of Tps.
31 and 32 N. Rs. 38 and 39 E.
Traces of old mound and pits
with piece of old post badly
decayed and with markings
obliterated.

The old line is a true
North and S line but all corners
are in a poor state of preservation
Some of them being entirely
obliterated I deem it necessary
to Resurvey this line in order
to preserve it - and to properly close
my survey. thereon.

(This is the old line found and reported
by G. O. Chaney U.S. Examiner of Surveys)