

Resurvey of Subdivisions of T. 37N. R. 60E.

chains From the cor. described I retrace N. on line bet. sec's 34 and 35

40.00 All trace of old $\frac{1}{4}$ sec. cor. has disappeared entirely

80.00 Old fence cor. lies 45 links east of line, intersection of N. and S. and E. and W. fences. This has been for more than twenty years the supposed location of the sec. cor. of sections 26, 27, 34 and 35 and has been accepted as such by the property owners on all sides.

I consider it unjust to make any change in the location of this point inasmuch as I am unable to find any trace of the old corner itself and I am informed by the old sellers that a stake was formerly at this point and that it was to the best of their recollection the location of the old cor. The line therefore between