

## Resurvey

265-

Outs. 230 N. R 34 E

Survey commenced June 20<sup>th</sup> with inst. fully described on page 1 notes of resurvey of 84<sup>th</sup> standard June 1<sup>st</sup> 1901.

At 7 am I set off  $23^{\circ}28'N$  on decl arc  $140^{\circ}$   
 $25'N$  on lat arc at Cor to 33084 & run  
 North bet Secs 33 & 34.

Ascending

40.00 Fall **2 lks** East of 4 sec. cor. which is a limestone near the shafts of the North Star & Inskip mines, marked & written as described by the Surveyor Genl. Repair the corner & from it continue to run North Course of true line  $N 0^{\circ}2'W$  along ridge mainly on west slope.

50.00 Int. cor to Secs 27, 28, 33 & 34 which is a limestone  $8 \times 12 \times 16$  ins marked, 1 notch on South & 3 on East. Mound destroyed I rebuild same 3 ft base & 2 ft high around cor. Course of true line North Pits impracticable  
 Land into **80.00 chs.**

Soil 3rd cut

Scattering cedars.