

Resurvey

Subs. T. 30 N. R 34 E

North bet Secs 304

1.50 Coyote Cr. 10 lts wide 1ft deep rec

2.00 Road nec rsw. Ascend

40.00 Falls. 20th W of 1/4 sec cor. nearly destroyed

Set limestone 8x10x15 ins mhd 4 on W for 1/4 sec. cor bet Secs 304 in md. stone 3ft base 2ft high.

N. 1° 43' E. = True Course ^{W. 1/4 Cor}

Pth impracticable Run N. from 1/4 Cor

61.00 Spur East

73.00 Draw W

80.00 Spur ESE

87.40 Int C.C. to Sec. 304 on Garland Much dilapidated. 6.95 lts. East Cor to Secs 330 34

At intersection Set limestone 6x8x14 ins mhd @ cond 3 notches E-W in mound stone 2ft base 2ft high for corners 304

Land mtb 87.40 chs.

Soil 3rd rate
Scattered cedars

At 5 pm set off 23° 28' N on decl arc and 40° 30' N on lat arc & find my meridian correct.

June 21st 1901