

347 11.

Resurvey of E. bdy. T. 7 N. R. 35 E

Chains. From the cor. to Tps. 6
and 7 N. Rqs. 35 and 36 E.
I run N. on blank line
on the east. bdy. sec. 36
at 40⁰⁴ chs. I find the $\frac{1}{4}$
sec. cor. at 6 lks. W. 80 chs.
no evidence of cor; and
continuing on the line
I find no traces of
obliterated corners
until at 400⁴⁰ chs. find
the cor. to secs. 1-12-6
and 7. at 70 lks. W. at 440
chs. no evidence of cor;
at 484⁶⁰ chs. intersect the
N. bdy. 84 lks. E. of cor. to
Tps. 7 and 8 N. Rqs. 35 and
36 E. which is a stone
6 x 16 x 10 ins. above ground,
marked as stated by
Surveyor General.
June 25-

I resurvey this range line
as follows:—
The old cor. to Tps. 7 and
8 N. Rqs. 35 and 36 E. is