

Resurvey of T. 33 N. R. 51 E. East Bdy.

N. bet. secs 1 and 6.

21.50 Ravine E.

26.50 Ridge E.

40.35 Intersect old $\frac{1}{4}$ sec. cor.,
which was a stake with
pits and mounds. Stake
fallen and greatly decayed.
Pits and mound obliterated.
Restore point.

40.00 Set Granite stone, $18 \times 12 \times 12$ ins.
in mound of stones, $2\frac{1}{2}$ ft
base, $1\frac{1}{2}$ ft high, marked
 $\frac{1}{4}$ on W. face, for $\frac{1}{4}$ sec cor
of secs. 1 and 6.

Pits impracticable

50.00 Ravine E.

54.00 Ridge E.

64.00 Ravine S. E.

73.00 Ridge E.

79.00 Intersect old Twp. cor.,
which was a stake with
pits and mound. Stake
fallen and greatly decayed.
Pits and mound obliterated.
Restore point.

Set Granite stone, $18 \times 12 \times 6$ ins.
in mound of stones, $2\frac{1}{2}$