

24 10
Resurvey W. Bdry T. 42 N., R. 34 E.

Where cors. are not set strictly in conformity with instructions in the Manual it was impracticable to do so, and they were set in the most durable manner possible as described. Mounds were of earth $5 \times 2\frac{1}{2}$ ft. and pits $18 \times 18 \times 12$, where size is not stated in the notes.