

Subdivisions of T₄₅N R₅₆E.

chains.

40.00

Set sandstone $18 \times 8 \times 5$ ins.,
 12 ins. in the ground for
 $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$
 on N. face; and raise a
 mound of stone, 2 ft. base, $1\frac{1}{2}$ ft.
 high, N. of cor.

46.75

Pits impracticable
 Enter heavy aspen timber
 bearing N and S.

67.75

Bottom of hollow, 150 ft. deep,
 course S.W.

Leave heavy timber bearing
 N.E. and S.W.

Enter scattering aspen
 timber

68.95

Wagon road bearing N.E. and
 S.W.

71.69

Intersect Ruby Valley Guide
 Meridian, 10.96 chs. N. of cor.
 of Secs. 30 and 31, which is a
 quartzite stone $8 \times 8 \times 6$ ins.

above ground, marked and
 witnessed as described by the
 Surveyor general. I destroy all marks
 on old cor. pertaining to R. 56 E.

Set quartzite stone, $20 \times 8 \times 6$
 ins., 15 ins. in the ground for