

2 464

Subdivision of T. 46 N. R. 55 E.

Chains

balance of the line to practically agree in course ^{and} chaining with the notes furnished by the Surveyor General ^{and} the Cors. were all found in good condition.

October 29, 1904

Oct. 30. As the S. bdy. of sec. 35 is not within limits in chaining, I establish a sectional Correction Line as follows:

At 8 a. m., l. m. 1, I set off $41^{\circ}50'$ N. on lat. arc: $13^{\circ}44'$ S. on decl. arc. ^{and} determine a meridian with the solar, at the Cor. of secs. 25, 30, 31 ^{and} 36, on the E. bdy. of the Twp. on the Ruby Valley Guide Meridian, hereafter described. Thence I run

West, on a sectional Correction Line,

bet. secs. 25 ^{and} 36.

Ascend along steep, south slope, through Sage ^{and} bunch grass.

40.00

Set a granite stone, $15 \times 8 \times 5$ ins. 10 ins.