

RE-SURVEY of SO. B'DY T. 19 N. R. 25 E.

- Chains. N. $88^{\circ}55'W$. on true line between
Secs. 6 and 31. over mountains
land descend
- 4.00 Road Bears N. $88^{\circ}55'W$ from Haddow
to Churchill.
- 6.00 Spur Bears S.W.
- 10.00 Wash, course East thence S.E.
- 40.34 The $\frac{1}{4}$ Sec. cor. of 6 and 31 - (on a
level spot, small wash 5 chs. north)
a basalt stone poorly marked
and mound destroyed -
Re-Establish as follows:-
Set a basalt stone $6 \times 8 \times 8$ ins.
12 ins. in ground - marked
with $\frac{1}{4}$ on N. face - build a
mound of stone around same
1 ft high ^{approx} raise a mound
of stone 3 ft. base $1\frac{1}{2}$ ft. high
North of cor.
Pits ^{in opposite} ~~there~~ over rolling land
N. $88^{\circ}55'W$. from $\frac{1}{4}$ Sec. cor.
- 80.24 The T.P. cor. of 18 and 19 W.
Tps. 24 and 256. - a stone
 $18 \times 10 \times 8$ ins. - in a mound
of stone - marked ^{with} 6 notches
N. E. S. $1\frac{1}{2}$ W. edges. I mark in
addition.