

RESURVEY
of

FOURTH STD. PAT. N. 71 through TR 26 E.

Chairs. Oct. 2-1905- 8:00 a.m. l.m.t.
 At the cor. of T. 21 N., R. 9 S. 26 and 27
 E. act re-established by run
 I lay off from the meridian an angle
 of 90° from N. to W. and
 run
 1/4 on tangent S. of Sec. 36 over
 Mountains Peak, ascending
 14.23 I find Closing Cor. of T. 19 N.
 R. 9 S. 26 and 27 E. - 25 Ks. S. of
 line - in bad condition
 a shattered limestone $12 \times 10 \times 8$
 ins. mxd. with 6 grooves on
 in S, E and W faces, surrounded
 by a few stones. not marked
 CC on S.E.C. I destroy
 and re-establish in same
 place as follows; Set a
 limestone $14 \times 10 \times 8$ ins. ^{9 ins. in ground} mxd.,
 with 6 grooves on S, E, and W
 faces. CC on S face. in
 a mound of stone and build
 a mound of stone 3 ft. base
 2 ft. high S. of Cor.
 Pits impracticable
 descend