

## Subdivision of T. 44 N., R. 56 E.

## Chains.

Soil, stony and sandy, 3rd. rate.

Undergrowth, sage brush, willows and bunch grass.

No timber.

Mountainous land, 27.10 chs.

West on sectional correction line bet. secs. 30 and 31.

Through scattering sage brush, over rolling land.

6.00 Ravine, 10 ft. deep. Course N.

14.20 Dry creek bed; course N.E.

18.00 Ascend about 150 ft. to

24.00 Top of spur, slopes S.; still ascending.

31.50 Top of ridge, bears N. and S.; about 75 ft. above top  
of spur.; descend about 150 ft. to

40.00 Set a granite stone, 15x11x5 ins., 10 ins. in the ground,  
for  $\frac{1}{4}$  sec. cor., marked  $\frac{1}{4}$  on N. face; and raise a  
mound of stone, 2 ft. base,  $1\frac{1}{2}$  ft. high, N. of cor.  
Pits impracticable.

40.52 Center of dry creek bed, course N.; about 5 ft. below  
 $\frac{1}{4}$  sec. cor.; ascend about 100 ft. to

48.00 Top of spur, bears N. and S.; descend.

60.00 Draw, course N.;

Spring 2.50 chs. N.; ascend about 50 ft. to

69.64 Intersect Ruby Valley Guide Meridian, 14.14 chs. N. of  
the cor. of secs. 30 and 31, which is a granite stone,  
10x9x7 ins. above ground, firmly set, and marked and  
witnessed as described by the surveyor general.

At point of intersection, set a granite stone 15x8x7 ins.  
10 ins. in the ground, for closing cor. of secs. 30 and  
31, marked C C on E.; with 5 grooves on N., and 1 groove  
on S. face; and raise a mound of stone, 2 ft. base,  $1\frac{1}{2}$   
ft. high, E. of cor. Pits impracticable.

I destroy all markings on the original Ruby Valley Guide  
Meridian cor. referring to secs. 30 and 31, leaving it  
as a monument of alignment only.

Land, mountainous and rolling.