

Resurvey of Subdivisions of T.17 N., R. 44 E.

Chains. N. $0^{\circ} 7'$ E. bet. secs. 1 and 2.

15.95 Water channel, course E.,

16.55 Road, bears E. and W.,

19.65 Road, bears N. 80° E., S. 80° W.,

28.75 Re-enter same road bears NW. and SE.

40.00 Find old stake, which I destroy, and re-establish at same point. Set a granite stone $15 \times 10 \times 8$ ins., 10 ins. in the ground for $\frac{1}{4}$ sec. cor. bet. secs. 1 and 2, marked $\frac{1}{4}$ on W. face and raise a mound of stones 2 ft. base, $1\frac{1}{2}$ ft. high, W. of cor. Pits impracticable.

52.85 Road, bears SE. and NW.,

59.30 Ravine, course SE.,

62.40 Road, bears NW. and SE.,

65.30 Road, bears E. and W.,

68.40 Road, bears NW. and SE.,

73.15 Birch Creek, course SE, 10 lks wide 1 ft. deep.

76.15 Road, bears NW. and SE.,

79.72 At this point I find old sec. cor. to secs. 1 and 2.

This cor. was originally set as the cor. to secs. 1, 2, 35 and 36, but the retracement and subsequent resurvey of a portion of the N. bdy. of this Tp. has shown the necessity for double cors. along this line, and this cor. should therefore now be described as the cor. to secs. 1 and 2.

Land mountainous.

Soil, stony, second rate.

Timber, sagebrush and willows.

Mountainous, covered with dense brush, very difficult to survey, 79.72 chs.