

Retracement of the S. bdy. of T 37 N, R 22 E, Mt. Diablo B. and M.

Chains.

Soil, rocky. 4th. rate.  
Vegetation, sagebrush and bunchgrass and mahoganys.  
Mountainous land 77.55 chs.

S 72°10'W bet. secs. 6 and 31.

Descending, over mountainous land.

7.15 Creek, 4 links wide, course N. Begin ascent of E. slope of mountain.

39.96 The 1-4 sec. cor., a post firmly set in the ground, badly decayed and the markings destroyed but witnessed as described by the Surveyor General.

I destroy all traces of the old corner and its accessories and re-establish it at the same point as follows.

Set a basalt stone, 18-9-7 ins., 12 ins. in the ground for 1-4 sec. cor., marked 1-4 on the N. face and raise a mound of stone 2 ft. base, 1 1-2 ft. high N. of cor.

Pits impracticable.

Continue ascent of mountain through mahogany trees.

53.50 Mountain spur, slopes S.E., begin descending.

66.50 The cor. of Tps. 36 and 37 N, Rs. 21 and 22 E, Mt. Diablo B. and M. This is a granite stone 9-7 ins. by 12 ins. above ground. Firmly set and marked and witnessed as described by the Surveyor General.

Land, mountainous.

Soil, rocky. 4th. rate.

Vegetation, sagebrush and bunchgrass and mahogany trees.

Mountainous land, 66.50 chs.

July 4, 1910.

July 5, 1910.

Retracement of the W. bdy. of T 37 N, R 22 E.

Mt. Diablo B. and M.

Since the S. bdy. is defective in alinement and measurement it will be necessary to establish a sectional Correction realinen and also to set closing corners on the W. bdy. for the cors. of sec. 30 and 31, 19 and 30, and etc.