

Resurvey of the W. bdy. of T 19 N, R 22 E,
west of secs. 7, 18, 19, 30 and 31.

chains.


S 0° 17' E on a true line bet. secs. 31 and 36.
Over mountainous land.

16.00 Mountain spur, slopes S. W.

35.36 The $\frac{1}{4}$ sec. cor.

I destroy all traces of this corner
and its accessories and re-establish
it at the same point as follows:

Set an iron post 3 ft. long, 1 in.
diam. 24 ins. in the ground for
 $\frac{1}{4}$ sec. cor. with brass cap mk'd.




and raise a mound of stone 2 ft.
base, $1\frac{1}{2}$ ft. high W. of cor.
S 0° 23' W, on a true line bet. secs.
31 and 36.

75.78 The cor. of T 19 N, Rs. 21 and 22 E.

I destroy all traces of this cor. and
its accessories and re-establish
it at the same point as follows:

Set an iron post, 3 ft. long, 3 ins.
diam. 24 ins. in the ground for
cor. of T 19 N, Rs. 21 and 22 E,
with brass cap mk'd.



and raise a mound of stone 2 ft. base
 $1\frac{1}{2}$ ft. high N. of cor.

Land, mountainous.

Soil rocky, 4th. rate, covered with basalt
rocks, fair growth sagebrush, little grass,
no timber, no mineral, land prac-
tically worthless.

June 7, 1911.