

Chains.

for cultivation. Good growth
sagebrush, little grass, no timber
Basalt mountains, no signs of
mineral, slopes westerly.


N 0.2' W on a true line bet. secs. 4 and 5

Over rolling mountains

5.00 Ravine, course S.W.

31.60 Low mountain spur, slopes S.E.

40.00 Set an iron post 3 ft. long, 1 in. diam.
24 ins. in the ground for $\frac{1}{4}$ sec. cor.
with brass cap mk'd.




and raise a mound of stone, 2 ft.
base, $1\frac{1}{2}$ ft. high W. of cor.

56.00 Ravine, course N.W., begin ascending
S. slope of basalt mountain.

78.82 I intersect the N. hdy. of the tps at W,
1.60 chs. from the cor. of secs. 32 and 33.
established by me June, 1911.

Set an iron post 3 ft. long, 2 ins.
diam. 24 ins. in the ground for
closing corner of secs. 4 and 5.
with brass cap mk'd.



and raise a mound of stone
2 ft. base, $1\frac{1}{2}$ ft. high S. of cor.
Land, rolling mountains.

Soil, rocky. 4th rate, wholly unfit
for cultivation, good growth sagebrush,
little grass, no timber. Basalt
mountains, land of very little
value. Slopes S. W.

July 28, 1911.