

Course.	Distance.	Latitude.		Departure.	
		North.	South.	East.	West.
E.Bdy-----	North-----	43.53	43.53		
N.Bdy-----	S 89° 57' W	21.26	00.02	21.26	
N.Bdy	S 89° 37' W	81.40	.54	81.40	
N.Bdy-----	S 89° 47' W	80.21	00.30	80.21	
N.Bdy-----	S 89° 49' W	79.80	00.26	79.80	
N.Bdy-----	S 89° 45' W	80.15	00.35	80.14	
N.Bdy-----	S 89° 42' W	80.78	00.42	80.78	
N.Bdy-----	S 89° 45' W	54.78	00.26	54.78	
W.Bdy-----	South-----	41.60	41.60		
S.Bdy-----	East-----	478.69		478.69	
Convergency-----					00.06
Total-----		43.53	43.75	478.69	478.43
Error in lat-----				478.43	
Error in dep.			.22		0.26

General Description

This township is rough and mountainous in the western part, rolling in the interior, and nearly level in the eastern, while meadow land is to be found in sec 35.

This township is well watered, by a No of small streams, small groves of Quaking-asp timber will be found along the streams. The soil in general is very poor. execpt along ths streams and meadow.

James.D.Archer.

U.S.Transitman.

July 16, 1911.