

Chains.

West., on the S. bdy. of sec. 33.

80.00

Set an iron post, 3ft. long, 3ins. diam., 24 ins. in the ground, for cor. of secs. 32 and 33. with brass cap mkd:

T 39 N	R 18 E
S 32	S 33
1911	

dig pits, 24x24x12 ins., in each sec. 6ft. dist., and and raise a mound of earth, 4ft. base, 2ft. high, N. of cor.

Land, level and mountainous.

Soil, clay, sand, loam and rocks. 1st. and 4th. rate.

No timber.

Sage brush, undergrowth, 64.66 chs.

Drainage. W..

West., on the S. bdy. of sec. 32.

Over level meadow.

22.03

Wire fence, bears N. 20° E. and S. 20° W., Leave meadow. and enter low sand dunes.

26.78

Leave sand dunes. and enter level alkali lake bed. bears. N. and S.

40.00

Set an iron post, 3ft. long, 1 in. diam., 24 ins. in the ground, for 1/4 sec. cor. with brass cap mkd:

S 32
1/4

1911

dig pits, 18x18x12 ins., E. and W., of post, 3ft. dist., and raise a mound of earth, 3-1/2 ft. base, 1-1/2 ft. high, N. of cor.