

Retracement of Subdivisional Lines in T.36 N., R.62 E.
Resurvey of N. Bdy. of T. 36 N., R. 62 E.

15.

Chains

brass cap mkd:

T37N	R62E
S35	S36
1915	

from which:

A pinon pine 10 ins. in dia., bears N.52°30'E., 25 lks. dist., mkd. T37NR62E S36BT.

A pinon pine 9 ins. in dia., bears N.41°30'W., 67 lks. dist., mkd. T37NR62E S35BT.

Land, heavily rolling.

Soil is very rocky. Many solid outcrops and small cliffs. Also lots of slide rock. Limestone and red volcanic rock. Pinon pine, cedar and mountain mahogany timber. Sagebrush and a little grass.

S.89°44'E. on a resurvey along the S. Bdy. of Sec.36. Over heavily rolling foot hills through dense timber.

7.00 Rocky spur, 55 ft. above section corner, bears S.
23.30 Little draw, 130 ft. below spur, bears S. Thence over rolling S. slope.

40.00 Set an iron post 3 ft. long, 1 in. in dia., 26 ins. in the ground for $\frac{1}{4}$ sec. cor. for sec. 36, with brass cap mkd:

$\frac{1}{4}$ S 36
1915

from which:

A pinon pine 9 ins. in dia. bears N.34°W., 24 lks. dist., mkd. $\frac{1}{4}$ S36BT.

69.70 Old wood road, bears N.20°E. and S.20°W.

80.00 The cor. of Ts. 36 and 37 N., Rs. 62 and 63 E., heretofore described. Corner is 170 ft. above draw.

Land heavily rolling.

Very rocky soil; many solid outcrops. Pinon pine and cedar timber. Sagebrush. A little grass.

June 2, 1915.

RETRACEMENT OF SUBDIVISIONAL LINES, T.36 N., R.62E.

April 26, 1915: At the old cor. of secs. 13, 18, 19 and 24, on the W. Bdy., which is a quartzite stone 18x17x14 ins. in a mound of stone, marked with 3 notches on the N. and S. edges, at 2 h 0 m p.m., l.m.t., I set off 41°00 $\frac{1}{2}$ 'N. on the lat. arc; 13°24'N. on the decl. arc; and determine a meridian with the solar.

39.50 Thence S.89°47'E. on retracement between secs. 18 and 19. After diligent search, I find no evidence of old $\frac{1}{4}$ cor.

79.50 After diligent search, I find no evidence of the old section corner. As this corner is in the center of an alfalfa field, it has been destroyed. Old settlers assert they have never known the position of this old corner.

40.00 S.89°47'E. on a retracement between secs. 17 and 20. After diligent search, I find no evidence of the old $\frac{1}{4}$ sec. cor.

80.00 After diligent search, I find no evidence of the old section corner.

81.10 A cedar post, which is not the original corner and cannot be identified as a section corner, bears N. 118 lks.
April 26, 1915.

April 27, 1915: At 8 h 0 m a.m., l.m.t., with instrument over above mentioned post, I set off 41°00 $\frac{1}{2}$ 'N. on the lat. arc; 13°38'N. on the decl. arc; and determine a meridian with the solar.