LATITUDES, DEPARTURES AND CLOSING ERRORS.						
		Latit		tudes	Departures	
Line Designated	Bearing	Dist.	N.	s.	E•	W
		Chs	Chs	Chs	Chs	Chs
CC of T38&39NR20E to Cor.of T38&39NR19E. S. \(\frac{1}{2}\) E.Bdy.sec.36 \(\frac{1}{4}\)cor.on E.Bdy.Sec.36	N.0°15'W. N.1°8'W.	11.26 39.66				.05
to 4 cor. on E.Bdy. 25 N. 2 E.Bdy. Sec. 25 S. 2 E.Bdy. Sec. 24 N. 2 E.Bdy. Sec. 24 S. 2 E.Bdy. Sec. 13	N.0°12'W. N.0°58'W. N.0°28'W.	39.97	40.03			.28 .68 .33
N. & E.Bdy. Sec. 24 S. & E.Bdy. Sec. 13 N. & E.Bdy. Sec. 13 S. & E.Bdy. Sec. 12	N.0°4'W. N.0°29'W. N.0°7'E. N.0°34'W.	40.36 40.19 40.18 40.24	40.19		.08	.40
N. ½ E.Bdy. Sec.12 S. ½ E.Bdy. Sec. 1 ½cor.on E.Bdy.sec.1 to	N.0°6'W. N.0°21'E.	40.18 39.97	40.18	*	. 24	.07
CC of T.39&39 NR20 E. N.Bdy.T.39NR20 E. E.Bdy.T.39 NR 20 E.	North East South	28.95 496.83 480.00		480.00	496.83	
SE.cor.of Tp.to cor.of secs.5,6,31 & 32 E. $\frac{1}{2}$ N.Bdy. Sec.6 W. $\frac{1}{2}$ N.Bdy. Sec.6		400.00 40.40 51.09		/01		400.00 40.40 51.09
Old CC of T38 &39 N,R 20E to new CC of same Convergency	West	3.11			.66	3.11
	Totals		480.20 480.01	480.01	497.58	497.58
Errors, - In lat19 In dep., .23						

GENERAL DESCRIPTION.

This township consists principally of high rolling hills. There is a flat basin in the northeastern part of the township, and there are several deep canyons in the southwestern part. The northwest and southeast corners of the township are very high. Wall Creek drains nearly the entire township, the waters of almost the entire east half being collected in the basin above referred to. This creek has a southwesterly course and leaves the township near the southwest corner. It has a valley varying in width from one to fifteen chains.

Wall Creek probably flows the year around. It is fed by a large number of fresh water springs, the principal one being in section 9. The township is well supplied with water. The soil of the basin in the northeast part of the township is partly adobe and partly a sandy loam. Where there is adobe soil there is some sagebrush and much rabbit brush. The loam soil produces heavy sagebrush. The valley of Wall Creek also produces good vegetation. The soil of the hilly portions of the township is also in many places a very fertile sandy loam, but so liberally strewn with rocks of varying size as to be worthless for agriculture.

There is a large patch of mahogany timber in the southeast corner of the township and an occasional mahogany and juniper tree here and there throughout the township; otherwise there is no timber. There are a few very small patches of willow and other brush on Wall Creek. There is excellent bunchgrass in many places in the township.