

SUBDIVISION OF T.16 N., R.22 E.

Chains

- 39.71 Point due W. of the $\frac{1}{4}$ sec. cor. on the E. bdy. of sec. 10,
I therefore at this point
Set an iron post, 3 ft. long, 1 in. dia., 26 ins. in the
ground, for $\frac{1}{4}$ sec. cor. of sec. 10, with brass cap mkd.;
- $\frac{1}{4}$ | S 10
1911;
- and raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high,
E. of cor.
- 58.60 Road to Hercules mine, bears N.W. and S.E.
- 67.40 Dry wash, 10 lks. wide, course, W.N.W.
- 78.05 Intersect the temp. cor. of secs. 9 and 10, which I make
the permanant cor. as follows:
Set a basalt rock, 24x24x7 ins., 18 ins. in the ground, for
cor. of secs. 9 and 10, mkd. with 4 notches on the
S. and 3 notches on the E. edges; and raise a mound of
stone, 2 ft. base, $1\frac{1}{2}$ ft. high, N. of cor. Iron post
impracticable.
- Land rolling.
Soil, part sandy loam; part rocky; 2nd. and 3rd. rate.
No timber; desert brush.

December 16, 1911.

GENERAL DESCRIPTION.

The eastern portion of the Tp. embraced in the foregoing
survey consists of very high, steep, rugged mountains.

The western portion consists of a nearly level flat,
portions of it rolling, all of which slopes gently to-
ward the Carson River.

There are two springs in sec 14 and one in sec. 15.

The soil consists mostly of rocks and boulders, except in
the extreme western portion, and in sec. 19 where there
is some cultivated land.

There is one settler in sec. 19.

There is no grass in the tp. except in sec. 19.

The most of the land in the flat is so extremely rocky, that
it is hardly fit for cultivation.