

Boundaries of T 25 N. R 26 E

Latitudes, Departures and closing errors.

Line designated.	True bearing.	Distance.	Latitudes.		Departures.	
			N	S	E	W
N. bdy. Sec. 1, 1.	N. 89° 42' W.	9.40	.05			9.40
N. bdy.	N 89° 50' W	469.74	1.33			469.74
		469.74	.03			
W. bdy	S.	486.82		486.82		
S bdy	E.				479.08	
E. bdy.	N		484.73			
Convergence						60
Totals			486.01	486.82	479.08	479.74
				486.01		479.08
Error in latitude.				.81	Error in dep.	.66

General Description.

This township is rolling hills, ridges, and ravines; in the southern and eastern part; and mountainous in the remaining portion.

The hills and mountains are all of granite; cut through in some places with quartz veins and volcanic dikes. In sections 3, 4, 9, 10, 16 and 30, are the most pronounced mineral indications. Copper indications predominate. No part of this township can be successfully cultivated without irrigation, and there is no water available for this purpose. The land is of some small value for grazing, the stock pasturing on the sagebrush, and what little grass and other herbage exists. There is no water in this township and no settlers. A number of mining claims have been located in the sections mentioned above as being mineralized.

Nov. 9, 1911.

Winfred A. Pray
Transitman, S. L. Co.