

Boundaries of T. 36 N, R. 32 E.
Latitudes, departures, and closing errors.

Line designated	True bearing	Distance	Latitudes		Departures	
			N	S	E	W
7th Standard Parallel		bhs.	bhs.	bhs.	bhs.	bhs.
N. along S. bdy. secs. 36 and 35	S. 89° 47' W.	160.00		.61		160.00
W. bdy. sec. 35 and 26	N. 0° 13' E.	160.00	160.00		.61	
N. bdy. sec. 26	N. 89° 45' E.	79.88	.35		79.88	
W. bdy. sec. 24 and 13	N. 0° 14' E.	160.00	160.00		.65	
N. bdy. sec. 13	N. 89° 49' E.	79.07	.25		79.07	
E. bdy. sec. 13 to 1/4 sec. cor. sec. 18	S 0° 33' W.	38.20		38.20		.37
S. 1/2 of W. bdy. sec. 18	S 0° 2' W.	40.28		40.28		.02
W. bdy. sec. 19, T36N, R32E	S 0° 8' E.	80.32		80.32	.18	
N. 1/2 of W. bdy. sec. 30.	S. 0° 2' W.	40.08		40.08		.02
S. 1/2 of W. bdy. sec. 30.	South.	40.20		40.20		
N. 1/2 of W. bdy. sec. 31.	South.	40.65		40.65		
S. 1/2 of W. bdy. sec. 31.	S 0° 8' E.	40.27		40.27	.09	
Convergency					.10	
Totals			320.60	320.61	160.58	160.41
				320.60	160.41	
Error in lat.				.01	.17	Error in dep.

General Description.

This fractional township is flat. The south western portion is entirely void of vegetation, it being the bed of a dry lake, which overflows with every rain storm. The remainder of the township is slightly higher, and is covered with a dense growth of greasewood. The soil is alkaline and absolutely worthless. There is no water in the township, nor are there any settlers.