

Subdivision of T31N, R38E.

Chains

Undergrowth, sage brush,  
No timber.

July-26-1913

Boundaries of T31N, R38E.  
Latitudes, departures and closing errors

Line Designated	True Bearing	Dist- ance	Latitudes		Departures	
			N	S	E	W
		chs.	chs.	chs.	chs.	chs.
W. Bdy of T31	North	320.00	320.00	---	---	---
N. " " 5.7	N89°43'E	77.92	.38	---	77.92	---
N. " " 5.8	N89°42'E	80.02	.42	---	80.02	---
N. " " 5.9	N89°43'E	80.26	.40	---	80.26	---
E. " " 5.9	S0°12'W	40.10	---	40.10	---	.14
E. " " 5.9	S0°04'E	40.07	---	40.07	.05	---
E. " " 5.16	S0°04'E	80.14	---	80.14	.09	---
S. " " 5.16	S89°53'W	80.28	---	.16	---	80.28
S. " " 5.19	S89°53'W	80.02	---	.16	---	80.02
E. " " 5.19 and 30	S0°01'W	160.00	---	160.00	---	.04
S. " " 5.30	S89°48'W	78.00	---	.27	---	78.00
Convergency	---	---	---	---	.13	---
Totals			321.20	320.90	238.47	238.48
			320.90			238.47
Errors in lat.			.30	Errors in Dep.		.01

General Description

The north and eastern part of this fractional township is level and rolling, and the remainder is mountainous. A high ridge bears N and S. in the west tier of the township, the mountains are of granite and volcanic formation. There are no surface indication of minerals being present, and no signs of any prospecting.