

Subdivision of T 40 N, R 32 E

chains.

$\frac{1}{4}$ sec. cor. east of sec. 36 is an iron post 3 ft. long, 1 in. diam. set 24 in. in the ground for $\frac{1}{4}$ sec. cor. E. of sec. 36 with brass cap mkd.

536 $\frac{1}{4}$ | ✓
1911

with mound of stone 2 ft. base, 1 $\frac{1}{2}$ ft. high W. of cor.

The cor. of Tps. 39 and 40 N, Rs. 31 and 32 E, I reestablished and changed to cor. of Tps. 39 and 40 N, R 31 E, on Sept 5, 1912, when running the S. ldy of T 40 N R 32 E Sept 28, 1912.

Boundaries of T 40 N R 32 E.
Latitudes, departures and closing errors.

Line designated	True bearing	Distance	Latitudes		Departures	
			N	S	E	W
W. ldy.	S	458.28		458.28		
S. ldy.	E	471.15			471.15	
E. ldy.	N	456.90	456.90			
Closing cor. T 40 N, R. 32-33 E to Standard cor. Secs. 32-33	N 89° W	330.93	5.80			330.93
Standard cor. Secs. 32-33 to Chain cor. T 40 N, R. 31-32 E	S 88° 20' W	139.18		4.05		139.18
Convergence						.63
Totals			462.70	462.33	471.15	470.74
Error in lat.			.37	Error in	41	
				diff.		

General Description.

Along Bottle creek in Secs. 23, 24 and 25, Mrs. Clara Hirschell has improved and cultivated whatever land is available for farming. In Secs. 4 and 5, along the two forks of Hoppy creek De Lang has some land in cultivation. In Secs. 4, 9 and 16 there is some more land which can be cultivated.