

Subdivision of T. 21 N., R. 69 E.

Chains.

- A pinion pine, 16 in. in diam., bears N. 47° W.,
19 lks. dist., marked $\frac{1}{4}$ S 6 E T.
- 51.80 Bottom of draw, 5 lks. wide, course S. 70° E.;
ascend.
- 54.20 Top of spur, slopes S. 80° E.
- 59.20 Bottom of draw, with stream of pure, cold
water, $\frac{1}{2}$ lk. wide, course S. 80° E.
- 62.20 Top of spur, slopes S. 80° E.; descend.
- 64.00 Dry wash, 5 lks. wide, 15 ft. deep, course
S. 80° E.
- 66.00 Bottom of draw, 20 lks. wide, course N. 45° E.;
ascend over very steep N. slope.
- 80.17 The cor. of secs. 5, 6, 7 and 8.
Land, rough mountainous.
Soil, decomposed granite; very rocky;
3rd. and 4th. rate; many granite
outcrops and cliffs; steep, precipitous
slopes; good grazing land.
Timber, mountain mahogany, pinion
pine, aspen and balsam fir.
Undergrowth, sagebrush, chokecherry,
serviceberry and willows.
Mountainous land, 80.17 chs.
Dense timber, 80.17 chs.

Sept. 11, 1913

Boundaries of T. 21 N., R. 69 E.

Latitudes, departures, and closing errors.

Line Designated	True bearing	Distance	Latitudes		Departures	
			N.	S.	E.	W.
4th. Standard Parallel N., through Range 69 E.	West	480.00				480.00
W. bdy, T. 21 N., R. 69 E.	North	480.00	480.00			
N. bdy, T. 21 N., R. 69 E.	East	478.75			478.75	
E. bdy, T. 21 N., R. 69 E.	South	480.00		480.00		
Convergence					.60	
Totals			480.00	480.00	479.35	480.00
Error in lat.			480.00			479.35
			0.00	Error in dep.		.65