

Chains

N. bet. secs. 7 and 12.

Ascending S.W. slope, over rolling land.

15.80 Ridge, bears NW. and SE. Descend gradually.

40.00 On NW. slope.

Set an iron post 3 ft. long, 1 in. dia., 24 ins. in the ground for $\frac{1}{4}$ sec.cor., with brass cap mkd:

S12 $\frac{1}{4}$	S7
1914	

and raise a mound of stone 2 ft. base, 1 $\frac{1}{2}$ ft.high, W. of cor.

49.50 Ravine, course NE. Asc.

55.60 Ridge, bears NE. and SW. Desc. NW. slope.

63.10 Draw, course NE. Ascend SE. slope.

68.00 Ridge, bears NE. and SW. Desc.

72.20 Ravine, course NE. Ascend SE. slope.

80.00 Set an iron post 3 ft. long, 3 ins. dia., 24 ins. in the ground for cor. of secs. 1, 6, 7 and 12; with brass cap mkd:

T 33 N	
R45E	R46E
S1	S6
S12	S7
1914	

and raise a mound of stone 2 ft. base, 1 $\frac{1}{2}$ ft. high, W. of cor.

Land; rolling ridges and ravines, sloping to the NE.

Soil; fair quality, coarse texture loam, from a few inches to a foot in depth, washed on the slopes. Contains considerable gravel and stone; underlaid with a firm, rocky, subsoil, 3rd rate. Good growth sagebrush, considerable grass, no timber.

N. bet. secs. 1 and 6.

Ascending SE. slope.

8.30 Ridge, bears E. and W. Descend.

23.90 Ravine, course NE. Ascend SE. slope.

40.00 On SE. slope.

Set an iron post 3 ft. long, 1 in. in dia., 24 ins. in the ground for $\frac{1}{4}$ sec.cor. with brass cap mkd:

S1 $\frac{1}{4}$	S6
1914	

and raise a mound of stone 2 ft. base, 1 $\frac{1}{2}$ ft. high W. of cor.