


E. bdy. of T 35 N, R 47 E.

Chains


18.60 Small ravine, course E. Asc. 80 ft. to
 24.30 Low spur, slopes N.E. Desc. 100 ft. to
 40.00 Set an iron post, 3 ft. long, 1 in. diam. 24 ins. in the
 ground for $\frac{1}{2}$ sec. cor. with brass cap mkd.



Dig pits 18-18-12 ins. N. and S. of post 3 ft. dist. and
 raise a mound of earth $3\frac{1}{2}$ ft. base $1\frac{1}{2}$ ft. high W. of cor.

Desc. 50 ft. to

57.00 Small ravine, course N.E. Asc. 20 ft. to
 64.35 Low, flat spur, slopes N.E. Desc. 60 ft. to
 80.00 Set an iron post, 3 ft. long 3 ins. diam. 24 ins. in the
 ground for cor. of secs. 1, 6, 7 and 12 with brass cap mkd.



dig pits 18-18-12 ins. in each sec. $5\frac{1}{2}$ ft. dist. and raise
 a mound of earth 4 ft. base, 2 ft. high W. of cor.

Land; rolling ridges and ravines, with a general easterly
 and N.E. slope.


Soil; fair quality desert loam, medium fine texture.

From 10 to 15 ins. in depth. Underlaid with a firm clay
 subsoil. Considerable amounts of rock and gravel. All
 very dry. Good growth sage brush, little grass.

N. bet. secs. 1 and 6

Over rolling ridges and ravines, sloping to the N.E.
 Desc. 20 ft. to

4.90 Small ravine, course N.E. Desc. 60 ft. to
 30.60 Wash, course N.E.
 40.00 Set an iron post 3 ft. long, 1 in. diam. 24 ins. in the
 ground for $\frac{1}{2}$ sec. cor. with brass cap mkd.



dig pits 18-18-12 ins. N. and S. of post 3 ft. dist. and
 raise a mound of earth $3\frac{1}{2}$ ft. base. $1\frac{1}{2}$ ft. high W. of cor.